

AutoCAD Commonly Used Hotkeys

L – LINE **C** – CIRCLE **A** - ARC

REC - RECTANGLE

E – ERASE

M – MOVE

CO – COPY (Ctrl + C, Ctrl + V to paste)

RO - ROTATE

SC – SCALE

TR – TRIM

EX – EXTEND

O – OFFSET

MI – MIRROR

F – FILLET

S – STRETCH

AR - ARRAY

U – UNDO (Ctrl + Z)

DI – DISTANCE, for checking measurements

DT – TEXT, SINGLE LINE

MT – TEXT, MULTI LINE

Ctrl + P – PLOT

AutoCAD Commonly Used Hotkeys

L – LINE **C** – CIRCLE **A** - ARC

REC - RECTANGLE

E – ERASE

M – MOVE

CO – COPY (Ctrl + C, Ctrl + V to paste)

RO - ROTATE

SC – SCALE

TR – TRIM

EX – EXTEND

O – OFFSET

MI – MIRROR

F – FILLET

S – STRETCH

AR - ARRAY

U – UNDO (Ctrl + Z)

DI – DISTANCE, for checking measurements

DT – TEXT, SINGLE LINE

MT – TEXT, MULTI LINE

Ctrl + P – PLOT

AutoCAD Commonly Used Hotkeys

L – LINE **C** – CIRCLE **A** - ARC

REC - RECTANGLE

E – ERASE

M – MOVE

CO – COPY (Ctrl + C, Ctrl + V to paste)

RO - ROTATE

SC – SCALE

TR – TRIM

EX – EXTEND

O – OFFSET

MI – MIRROR

F – FILLET

S – STRETCH

AR - ARRAY

U – UNDO (Ctrl + Z)

DI – DISTANCE, for checking measurements

DT – TEXT, SINGLE LINE

MT – TEXT, MULTI LINE

Ctrl + P – PLOT